

# Lexmark Security Advisory:

Revision: 1.0  
Last update: 10 May 2017  
Public Release Date: 25 May 2017

## Summary

Some Lexmark products have a remote code execution vulnerability that allows a remote attacker to execute arbitrary code on the device.

## References

CVE: CVE-2016-10229

## Details

A vulnerability in udp.c in the Linux kernel before 4.5 allows remote attackers to execute arbitrary code via UDP traffic that triggers an unsafe second checksum calculation during execution of a recv system call with the MSG\_PEEK flag.

**CVSS v3 Base Score:** 9.8 Critical (AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H)

Impact Score: 5.9

Exploitability Score: 3.9

**CVSS v2 Base Score:** 10.0 HIGH (AV:N/AC:L/Au:N/C:C/I:C/A:C)

Impact Subscore: 10.0

Exploitability Subscore: 10.0

CVSSv3 scores are calculated in accordance with CVSS version 3.0  
(<https://www.first.org/cvss/user-guide>)

CVSSv2 scores are calculated in accordance with CVSS version 2.0  
(<https://www.first.org/cvss/v2/guide>)

## Impact

This vulnerability can lead to the unauthorized disclosure of configuration information and user data on the affected device.

## Affected Products

To determine a device's firmware level, select the **Settings > Reports > Menu Setting Page** menu item from the operator panel. If the firmware level listed under "**Device Information**" matches any level under "**Affected Releases**", then upgrade to a "**Fixed Release**".

| <b>Lexmark Models</b>           | <b>Affected Releases</b> | <b>Fixed Release</b>  |
|---------------------------------|--------------------------|-----------------------|
| CX820de, CX820dtfe              | PP.033.115 and previous  | PP. 033.116 and later |
| XC6152de, XC6152dtfe            | PP.033.115 and previous  | PP.033.116 and later  |
| CX825de, CX825dte,<br>CX825dtfe | PP.033.115 and previous  | PP.033.116 and later  |
| XC8155de, XC8155dte             | PP.033.115 and previous  | PP.033.116 and later  |
| CX860de, CX860dte,<br>CX860dtfe | PP.033.115 and previous  | PP.033.116 and later  |
| XC8160de, XC8160dte             | PP.033.115 and previous  | PP.033.116 and later  |
| CS820de, CS820dte,<br>CS820dtfe | YK.033.115 and previous  | YK.033.116 and later  |
| C6160                           | YK.033.115 and previous  | YK.033.116 and later  |
| CS720de, CS720dte               | CB.033.115 and previous  | CB.033.116 and later  |
| CS725de, CS725dte               | CB.033.115 and previous  | CB.033.116 and later  |
| C4150                           | CB.033.115 and previous  | CB.033.116 and later  |
| CX725de, CX725dhe,<br>CX725dthe | ATL.033.115 and previous | ATL.033.116 and later |
| XC4150                          | ATL.033.115 and previous | ATL.033.116 and later |

## ***Obtaining Updated Software***

To obtain firmware that resolves this issue, or if you have special code, please contact Lexmark's Technical Support Center at <http://support.lexmark.com> to find your local support center.

## ***Workarounds***

Lexmark recommends updating firmware to address this issue.

## ***Exploitation and Public Announcements***

Lexmark is not aware of any malicious use against Lexmark products of the vulnerability described in this advisory.

## ***Status of this Notice:***

THIS DOCUMENT IS PROVIDED ON AN "AS IS" BASIS AND IS PROVIDED WITHOUT ANY EXPRESS OR IMPLIED GUARANTEE OR WARRANTY WHATSOEVER, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR USE OR PURPOSE.

## ***Distribution***

This advisory is posted on Lexmark's web site at <http://support.lexmark.com/alerts>  
Future updates to this document will be posted on Lexmark's web site at the same location.

## ***Revision History***

| <b><u>Revision</u></b> | <b><u>Date</u></b> | <b><u>Reason</u></b>   |
|------------------------|--------------------|------------------------|
| 1.0                    | 25 May 2017        | Initial Public Release |